



# S&S MECHANICAL

**S&S Mechanical**  
4831 South Crain Highway  
Upper Marlboro, MD 20772

Tel. 1 - (301) 574-1555  
Fax. 1 - (301) 574-1558  
www.sandsmidatlantic.com

## CUSTOMER QUOTATION NO. 1035

CMI Management, Inc.  
5285 Shawnee Road Suite #510  
Alexandria VA 22312

**Quote Name:** 17757  
**Quote No:** 1035  
**Site:** MD066 Fox Tail Avenue  
**Site Contact:**  
**Salesperson:** Lindsay Ruby  
**Created Date:** 05/17/2022  
**Valid For:** 30 Day(s)

**WO#: 17757**

**CSS Ticket Number: 560**

**Problem:** Air handler leaking water in room 208, Repair leaks and Replace ceiling tiles. Get info on ceiling tiles\*  
POC SGT Simms her number is 910-598-8410

S&S proposes to remove and replace (2) control boards in the Daikin Unit. HP 2-17.  
S&S will then complete a system check to ensure everything is working properly.

### Service

Item	Quantity	Unit Price	Total
668105801 Control Board	1.00	\$504.00	\$504.00
668105601 Control Board	1.00	\$162.23	\$162.23
Ceiling tiles	1.00	\$54.74	\$54.74
Diagnosis Fee	1	\$450.00	\$450.00
HVAC Labor Rate	12	\$100.00	\$1,200.00
<b>Sub-Total ex Tax</b>			\$2,370.97
<b>Tax</b>			\$0.00
<b>Total inc Tax</b>			\$2,370.97
<b>Labor</b>			\$1,650.00
<b>Materials</b>			\$720.97
<b>Sub-Total ex Tax</b>			\$2,370.97
<b>Tax</b>			\$0.00
<b>Total inc Tax</b>			\$2,370.97