



CUSTOMER QUOTATION NO. 120

CMI Management, Inc.
CMI Management, Inc.
Richard Hicks
5285 Shawnee Road Suite #510
Alexandria VA 22312

Quote Name: 11271
Quote No: 120
Site: MD021 Baltimore Road
Site Contact: Rick Hicks
Salesperson: Lindsay Ruby
Created Date: 11/12/2019
Valid For: 30 Day(s)

WO# 11271

CSS Ticket Number: 22268

Problem: Smell of gas when near unit. Unit tripping off some safety issue. Diagnosed a bad fan pressure switch, or flame controller ,and or flame sensor.

S & S proposes to remove and replace the following materials on the MAU Unit at MD021. S & S will then complete a system check to ensure everything is running correctly.

Service

Item	Quantity	Unit Price	Total
Diagnostic	1.00	\$400.00	\$400.00
Contactor	1.00	\$484.49	\$484.49
Overload Relay	1.00	\$119.30	\$119.30
Shipping	1.00	\$150.00	\$150.00
HVAC Labor Rate	6	\$100.00	\$600.00
Sub-Total ex Tax			\$1,753.79
Tax			\$0.00
Total inc Tax			\$1,753.79

Labor	\$600.00
Materials	\$1,153.79
Sub-Total ex Tax	\$1,753.79
Tax	\$0.00
Total inc Tax	\$1,753.79