



## CUSTOMER QUOTATION NO. 128

CMI Management, Inc.  
5285 Shawnee Road Suite #510  
Alexandria VA 22312

**Quote Name:** 11416  
**Quote No:** 128  
**Site:** MD066 Fox Tail Avenue  
**Site Contact:**  
**Salesperson:** Lindsay Ruby  
**Created Date:** 11/21/2019  
**Valid For:** 30 Day(s)

**WO# 11416**

**CSS Ticket Number: 22599**

**Problem: Need to install a drain line in the cooling tower for proper upkeep.**

S & S proposes to drain the cooling towers. S & S will then install a new drain line to the plugged outlet at the bottom of the cooling tower and run the piping away from the building and towards the parking lot.

### Service

Item	Quantity	Unit Price	Total
Diagnostic	1.00	\$200.00	\$200.00
3" PVC	1.00	\$39.86	\$39.86
3" PVC Ball Valve	1.00	\$59.14	\$59.14
3" PVC 45	1.00	\$6.18	\$6.18
3" PVC Street 45	1.00	\$8.72	\$8.72
3" PVC 90	1.00	\$7.90	\$7.90
3" PVC Male Adapter	1.00	\$5.06	\$5.06
Shipping	1	\$50.00	\$50.00
Plumbing Labor Rate	8	\$100.00	\$800.00
<b>Sub-Total ex Tax</b>		\$1,176.86	
<b>Tax</b>		\$0.00	
<b>Total inc Tax</b>		\$1,176.86	

<b>Labor</b>	\$800.00
<b>Materials</b>	\$376.86
<b>Sub-Total ex Tax</b>	\$1,176.86
<b>Tax</b>	\$0.00
<b>Total inc Tax</b>	\$1,176.86