



CUSTOMER QUOTATION NO. 140

CMI Management, Inc.
5285 Shawnee Road Suite #510
Alexandria VA 22312

Quote Name: 11454
Quote No: 140
Site: MD066 Fox Tail Avenue
Site Contact:
Salesperson: Lindsay Ruby
Created Date: 12/12/2019
Valid For: 30 Day(s)

WO#: 11454

CSS Ticket Number: 22766

Problem:

Replace ballast in the following areas:

- (1) One is in the gym.
- (2) One is in the women's latrine/ locker room next to the gym
- (3) staircase B near the gym. I have small piece of blue tape on each
- (4) Room 130

S & S proposes to furnish and install the following:

S & S will remove the bad ballast in all the above locations.

S & S will then install new ballasts and check the operation to ensure it is working properly.

Service

Item	Quantity	Unit Price	Total
Diagnosis Fee	1.00	\$350.00	\$350.00
Battery Pack/ 82047672989	1.00	\$229.36	\$229.36
Ballast/ 78108706912	4.00	\$12.97	\$51.88
Tax	1.00	\$12.12	\$12.12
Shipping	1.00	\$100.00	\$100.00
Electrical Labor Rate	8	\$100.00	\$800.00
		Sub-Total ex Tax	\$1,543.36
		Tax	\$0.00
		Total inc Tax	\$1,543.36

Labor	\$800.00
Materials	\$743.36
Sub-Total ex Tax	\$1,543.36
Tax	\$0.00
Total inc Tax	\$1,543.36