



CUSTOMER QUOTATION NO. 283

CMI Management, Inc.
5285 Shawnee Road Suite #510
Alexandria VA 22312

Quote Name: 12346
Quote No: 283
Site: MD066 Fox Tail Avenue
Site Contact:
Salesperson: Lindsay Ruby
Created Date: 06/19/2020
Valid For: 30 Day(s)

WO#: 12346

Problem: A Load High Pitched squeak coming from a vent down stairs near the electrical room. Could be a bearing.

S&S was onsite and diagnosed that pump 2 has a bad motor and will need to be replaced. S&S also changed the belts and switched operations to pump 1 until repairs to pump 2 are made. S&S will then complete a system check to ensure everything is working properly.

Service

Item	Quantity	Unit Price	Total
Diagnostic	1.00	\$560.89	\$560.89
01018OT3E215TC-S-WEG 10HP	1.00	\$1,389.16	\$1,389.16
Tax	1.00	\$69.46	\$69.46
Shipping	1.00	\$100.00	\$100.00
HVAC Labor Rate	10	\$100.00	\$1,000.00
		Sub-Total ex Tax	\$3,119.51
		Tax	\$0.00
		Total inc Tax	\$3,119.51

Labor	\$1,000.00
Materials	\$2,119.51
Sub-Total ex Tax	\$3,119.51
Tax	\$0.00
Total inc Tax	\$3,119.51