



# S&S MECHANICAL

**S&S Mechanical**  
4831 South Crain Highway  
Upper Marlboro, MD 20772

Tel. 1 - (301) 574-1555  
Fax. 1 - (301) 574-1558  
www.sandsmidatlantic.com

## CUSTOMER QUOTATION NO. 508

CMI Management, Inc.  
5285 Shawnee Road Suite #510  
Alexandria VA 22312

**Quote Name:** 13641  
**Quote No:** 508  
**Site:** MD066 Fox Tail Avenue  
**Site Contact:**  
**Salesperson:** Lindsay Ruby  
**Created Date:** 02/10/2021  
**Valid For:** 30 Day(s)

**WO#: 13641**

**CSS Ticket Number: 28869**

**Problem:** Cooling tower at MD066 and found the basin iced over. We need a corrective maintenance ticket created to check the basin heater. Asset #md066-197.

S&S was onsite and found the class two transformer in the heater control box was not working.

S&S proposes to remove and replace the transformer.

S&S will then complete a full system check to ensure everything is running properly.

### Service

Item	Quantity	Unit Price	Total
Transformer/1007182	1.00	\$111.60	\$111.60
Shipping	1.00	\$25.00	\$25.00
Diagnosis Fee	1	\$400.00	\$400.00
HVAC Labor Rate	6	\$100.00	\$600.00
<b>Sub-Total ex Tax</b>			\$1,136.60
<b>Tax</b>			\$0.00
<b>Total inc Tax</b>			\$1,136.60

<b>Labor</b>	\$1,000.00
<b>Materials</b>	\$136.60
<b>Sub-Total ex Tax</b>	\$1,136.60
<b>Tax</b>	\$0.00
<b>Total inc Tax</b>	\$1,136.60