



S&S MECHANICAL

S&S Mechanical
4831 South Crain Highway
Upper Marlboro, MD 20772

Tel. 1 - (301) 574-1555
Fax. 1 - (301) 574-1558
www.sandsmidatlantic.com

CUSTOMER QUOTATION NO. 576

CMI Management, Inc.
5285 Shawnee Road Suite #510
Alexandria VA 22312

Quote Name: 13988
Quote No: 576
Site: MD066 Fox Tail Avenue
Site Contact:
Salesperson: Lindsay Ruby
Created Date: 04/15/2021
Valid For: 30 Day(s)

WO#: 13988

CSS Ticket Number: 30083

Problem: Urinal not flushing second floor.

After trying to change the batteries in the automated valve that did not fix the issue. There seems to be some type of electrical connection that is corroded.

S&S proposes to remove and replace the automatic Sloan flush valve.

S&S will then check to ensure the urinal is now fully operational.

Service

Item	Quantity	Unit Price	Total
RESS-C SLOAN AUTOMATIC FLUSH VALVE HEAD	1.00	\$434.53	\$434.53
Shipping	1.00	\$100.00	\$100.00
Diagnosis Fee	1	\$300.00	\$300.00
Plumbing Labor Rate	4	\$100.00	\$400.00
Sub-Total ex Tax			\$1,234.53
Tax			\$0.00
Total inc Tax			\$1,234.53

Labor	\$700.00
Materials	\$534.53
Sub-Total ex Tax	\$1,234.53
Tax	\$0.00
Total inc Tax	\$1,234.53