



## CUSTOMER QUOTATION NO. 580

CMI Management, Inc.  
5285 Shawnee Road Suite #510  
Alexandria VA 22312

**Quote Name:** 13859  
**Quote No:** 580  
**Site:** MD066 Fox Tail Avenue  
**Site Contact:**  
**Salesperson:** Lindsay Ruby  
**Created Date:** 04/22/2021  
**Valid For:** 30 Day(s)

**WO#:** 13859

**CSS Ticket Number:** 29391

**Problem:** Location is in the storage/cage area of bldg.1. Back near the offices. Unit is running but louvers are not open. BLDG EMS has fan in alarm.

S&S was onsite and found that the damper motor in the unit had no response.

S&S proposes to remove and replace the damper motor.

S&S will then complete a system check to ensure the system is running correctly.

Previous investigation in the total of \$700.00 from quote 547, further labor was needed to troubleshoot with TMI.

### Service

Item	Quantity	Unit Price	Total
GMA221.1U 2PT SR,120V,62LBIN	1.00	\$233.34	\$233.34
Shipping	1.00	\$50.00	\$50.00
HVAC Labor Rate	9	\$100.00	\$900.00
Diagnosis Fee	1	\$700.00	\$700.00
		<b>Sub-Total ex Tax</b>	\$1,883.34
		<b>Tax</b>	\$0.00
		<b>Total inc Tax</b>	\$1,883.34
		<b>Labor</b>	\$1,600.00
		<b>Materials</b>	\$283.34
		<b>Sub-Total ex Tax</b>	\$1,883.34
		<b>Tax</b>	\$0.00
		<b>Total inc Tax</b>	\$1,883.34