



## CUSTOMER QUOTATION NO. 582

CMI Management, Inc.  
5285 Shawnee Road Suite #510  
Alexandria VA 22312

**Quote Name:** 14140  
**Quote No:** 582  
**Site:** MD066 Fox Tail Avenue  
**Site Contact:**  
**Salesperson:** Lindsay Ruby  
**Created Date:** 04/22/2021  
**Valid For:** 30 Day(s)

**WO#:** 14140

**CSS Ticket Number:** 30139

**Problem:** CHEM line is broke to the cooling tower.

S&S proposes to isolate and repair broken pipe that feeds treatment to the cooling tower. Once repaired, will secure heat trace, insulation back on along with outer aluminum coverings. Will turn back on treatment and make sure it is working without issue.

### Service

Item	Quantity	Unit Price	Total
Schedule #80 PVC	1.00	\$8.78	\$8.78
3/4" PVC Female Connector	2.00	\$3.97	\$7.94
Pipe Cement	1.00	\$8.65	\$8.65
Aluminum Covering Bands	1.00	\$8.50	\$8.50
Diagnosis Fee	1	\$300.00	\$300.00
Plumbing Labor Rate	6	\$100.00	\$600.00
<b>Sub-Total ex Tax</b>			\$933.87
<b>Tax</b>			\$0.00
<b>Total inc Tax</b>			\$933.87

<b>Labor</b>	\$900.00
<b>Materials</b>	\$33.87
<b>Sub-Total ex Tax</b>	\$933.87
<b>Tax</b>	\$0.00
<b>Total inc Tax</b>	\$933.87