

Facility Repair Proposal

Region: 4A
Fac ID: PA118
Date: 1/18/23

CSS # 91444
Maximo Work Order No.: 11768

Asset ID: NA

Original Work Request:
Remove Sewage at Lift Station (Emergency)

Description of Repairs Needed:
Labor approximately (18) hours and material to a.) remove the sewage from the hole located next to the sewage lift station vault and remove sewage from vault. b.) Clear out drain at bottom of vault to ensure sewage is flowing into grate and into the vault. Approx gallons is 1,000 gallons of sewage.

Parts List: NA

Equipment List:
Pressure Washer
Air Gas Monitor
Pump

PM History:
NA

Cost Proposal:
See attached RS Means Estimate.

Total Cost: \$3764.09

Estimate Name: CSS 91444 - WO 11768 - PA118 Remove Sewage at Lift Station

ESTIMATE INFORMATION

Client Name: 99th
Estimate Address: 6467 Mikewood Blvd, Conneaut Lake, PA, 16316-6661
Type: Unit
Measurement System: US Standard
Notes:

COST DATA

Estimate Summary:						Catalog: Facilities and Commercial Renovation	
						Format: MasterFormat 2018	
						Release: Year 2023	
						Labor Type: Repair & Remodeling	
						City Cost Index: PENNSYLVANIA / OIL CITY (163)	

Before



Before



Before




Before



Before



KeyStone Ordinance
1-10-23




During

After



After



After

