

**Additional Funding Request
REVISED**

Submitted: 10/12/2021

MD066-Non-Functioning Lock	CSS #32584 WO#15109											
Description of Repairs	S&S proposes to replace the lock set on the OMG building.											
Original SC Investigative Diagnosis	\$320											
Diagnosis: Initial Work Order	There is a non-functioning CAC lock in the OMS building. It is an exterior lock that is not securing. The unit has positioned in front of the door so that I cannot be opened											
Explanation of Additional Costs for Repairs	N/A											
Additional Material Cost to Perform Repairs	Materials: \$ 816.00 <table border="1" data-bbox="628 1013 1476 1193"> <thead> <tr> <th>ITEM</th> <th>QUANTITY</th> <th>UNIT PRICE</th> <th>TOTAL</th> </tr> </thead> <tbody> <tr> <td>Lock Set</td> <td>1</td> <td>816.00</td> <td>\$816.00</td> </tr> </tbody> </table>				ITEM	QUANTITY	UNIT PRICE	TOTAL	Lock Set	1	816.00	\$816.00
ITEM	QUANTITY	UNIT PRICE	TOTAL									
Lock Set	1	816.00	\$816.00									
Additional Labor Cost to Perform Repairs	Labor: \$400.00 5 hours each/General Maint Rate \$80.00 per hour = \$400.00											
Total Cost of Repair	\$1536.00											