

## JOB ESTIMATE

# T&T Contracting

5318 Big Tyler Rd  
Cross Lanes, WV 25313

Date 29-Jul-2019

## International Support Group

## Site Location

9050 Pines Blvd # 150  
Pembroke Pines, FL 33024

748 N. Jefferson St  
Lewisburg, WV 24901

## Job Description

Due to the deterioration of the locking mechanism the window will not be able to be fix.

We recommend and offer this estimate to have the window replaced.

## Itemized Estimate

## NOTE

This is an estimate, not a contract for services. This estimate is for completing the job as described above. It is based on our evaluation and does not include material price increases or additional labor and materials which may be required should unforeseen problems arise after the work has started.

***Thank You For Your Business!***