



Date: 5/8/2023

Region: 4C

FAC ID: VA012

CSS No.: 92493

Maximo Work Order No.: 12361

Asset #: NA

Original Work Request:

No Hot Water, Replace Circulating Pump

Description of Repairs Needed:

Labor and material to a.) replace the 52722512 Grundfos Circulator Pump - CROSS PUMP

Material List:

(1) 52722512 Grundfos Circulator Pump

Equipment List:

NA

PM WO History:

NA

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
3	\$385.00	\$630.44	\$1,015.44