



Date: 5/26/2023

Region: 4C
FAC ID: WV006

CSS No.: 92912
Maximo Work Order No.: 12558

Asset #: NA

Original Work Request:

The rollup door in room 182 of the training building has a missing roller and the cable has come off the spool, the repairs that are needed are on the left side of door looking from inside this is the Cardio room

Description of Repairs Needed:

Labor and material to a.) put the roller on the door b.) put cable back on the door and c.) apply tension

Material List:

NA

Equipment List:

NA

PM WO History:

NA

Estimate Summary:

| Labor Hours | Labor | Material/Equipment | Total Repair |
|-------------|----------|--------------------|--------------|
| 2 | \$300.00 | \$0.00 | \$300.00 |