



Date: 3/6/2023

Region: 4C
FAC ID: WV035

CSS No.: 90888
Maximo Work Order No.: 11490

Asset #: NA

Original Work Request:

PTAC has a busted pipe, unable to stop the water from coming out

Description of Repairs Needed:

Labor and material to a.) repairing the hot water piping. b.) Repairs include tying the supply and return back together where the coil was taken out, and adding shut off valves to keep the system from having to be drained again.

Material List:

Valves
Pipe Fittings

Equipment List:

NA

PM WO History:

NA

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
24	\$3,537.04	\$1,790.33	\$5,327.37





© 1990
CHARLES
SCHROEDER
"ORIGINAL"
SCHROEDER

NIBCO
ELKHART, INDIANA
OFF

1D