

Facility Repair Proposal

Region: 4C
Fac ID: WV010
Date: 12/1/22

CSS # 90665
Maximo Work Order No.: 11469

Asset ID: NA

Original Work Request:
Replace Repair booster pump on boiler #3

Description of Repairs Needed:
Labor to a.) replace the booster pump with a like for like pump, Hydronic Circulating Pump: Std, Taco, Flanged, 1/6 HP, 33 ft Max. Head, 6 1/2 in Face to Face

Parts List: Taco Circulating Pump #0013-F3

Equipment List: NA

PM History:
NA

Cost Proposal:
See attached RS Means Estimate.

Total Cost: \$1,266.74

ESTIMATE INFORMATION

Notes:

COST DATA


Catalog:	Facilities and Commercial Renovation
Format:	MasterFormat 2018
Release:	Year 2022 Quarter 4
Labor Type:	Repair & Remodeling
City Cost Index:	WEST VIRGINIA / CLARKSBURG (263-264)

****Total** column values include the cost of Exception lines that may not be included in the Material, Labor and Equipment totals.

LEGEND

ESTIMATE

Grand Total	\$	1,027.94	\$	715.80	\$	312.14	\$	-	\$	1,027.94	\$	1,266.74	\$	787.38	\$	479.36	\$	-	\$	1,266.74
--------------------	----	-----------------	----	---------------	----	---------------	----	----------	----	-----------------	----	-----------------	----	---------------	----	---------------	----	----------	----	-----------------



GRUNDFOS

NONSUBMERSIBLE CIRCULATION PUMP

Type UP 26-99 F

P/N: 52722361 P1

PC 0804 TC

115 V
60 Hz
10 uF

1 PH

US

Class F
THERMALLY
PROTECTED

FOR INDOOR USE ONLY

$I_L(A)$	$P_i(W)$
2.15	245

MAX FLUID TEMP. 230 F

