



Facility Repair Proposal

Region: 4C
Fac ID: WV029
Date: 12/9/22

CSS # 90668
Maximo Work Order No.: 11471

Asset ID: NA

Original Work Request:
Repair two circulating pumps in OMS.

Description of Repairs Needed:
Labor (4) hours to a.) investigate the controls issues with the pumps and relays.

Parts List: NA

Equipment List: NA

PM History:
NA

Cost Proposal:
See attached RS Means Estimate.

Total Cost: \$882.56

Estimate Name: CSS 90668 - WO 11471 - WV029 Repair Circulating Pumps

ESTIMATE INFORMATION

Client Name: 99th
Estimate Address:
Type: Unit
Measurement System: US Standard
Notes:

COST DATA

Estimate Summary:							Catalog:	Facilities and Commercial Renovation	
							Format:	MasterFormat 2018	
							Release:	Year 2022 Quarter 4	
							Labor Type:	Repair & Remodeling	
							City Cost Index:	WEST VIRGINIA / CLARKSBURG (263-264)	





125
125
125
125

PUMP 2



PUMP-2

C09547505400100700000007

MEI Serial Number: EC07809-1

WV029-001

Asset#7139 Circ Pump-2