

Facility Repair Proposal

Region: 4C
Fac ID: VA051
Date: 12/2/22

CSS # 90823
Maximo Work Order No.: 11475

Asset ID: NA

Original Work Request:

Heating system is needing to be restored due to gas being shut off.

Description of Repairs Needed:

Labor and material to a.) restore building heat due to gas getting shut off at property. B.) Boilers are back in service but had to be shut back down due to Main HWP#4 leaking.

Parts List: NA

Equipment List: NA

PM History:
NA

Cost Proposal:

See attached RS Means Estimate.

Total Cost: \$1090.60

Estimate Name: CSS 90823 - WO 11475 - VA051 Restore Building Heat

ESTIMATE INFORMATION

Client Name: 99th
Estimate Address: 1915 Roanoke Boulevard, Salem, VA 24153-6408
Type: Unit
Measurement System: US Standard
Notes:

COST DATA

Estimate Summary:						Catalog: Facilities and Commercial Renovation	
						Format: MasterFormat 2018	
						Release: Year 2022 Quarter 4	
						Labor Type: Repair & Remodeling	
						City Cost Index: VIRGINIA / ROANOKE (240-241)	