



Date: 3/14/2023

Region: 4C  
FAC ID: WV029

CSS No.: 90824  
Maximo Work Order No.: 11819

Asset #: NA

**Original Work Request:**

Repair VAV sensor in room 215, VAV #82

**Description of Repairs Needed:**

Labor to a.) troubleshoot the VAV sensor in VAV #82 that serves Room 215.

**Material List:**

NA

**Equipment List:**

NA

**PM WO History:**

NA

**Estimate Summary:**

Labor Hours	Labor	Material/Equipment	Total Repair
8	\$1,162.70	\$0.00	\$1,162.70