

Facility Repair Proposal

Region: 4A
Fac ID: PA118
Date: 12/15/22

CSS # 90861
Maximo Work Order No.: 11489

Asset ID: NA

Original Work Request: Repair 3-inch-high pressure sewer line that comes from the sewage lift station that is broken.-Still waiting for a proposal

Description of Repairs Needed:

Labor and material to a.) enter the confined space and perform an initial investigation by scoping the lines with a camera.

Parts List:

Misc Fittings and Pipe

Specialty Confined Space Tools

Equipment List: NA

PM History:
NA

Cost Proposal:

See attached RS Means Estimate.

Total Cost: \$4067.26

Estimate Name: CSS 90861 - WO 11489 - PA118 Sewer Line Repair

ESTIMATE INFORMATION

Client Name: 99th
Estimate Address: 6467 Mikewood Blvd, Conneaut Lake, PA, 16316-6661
Type: Unit
Measurement System: US Standard
Notes: This work is to investigate and determine the location of the sewer line break.

COST DATA

Estimate Summary:						Catalog: Facilities and Commercial Renovation	
						Format: MasterFormat 2018	
						Release: Year 2022 Quarter 4	
						Labor Type: Repair & Remodeling	
						City Cost Index: PENNSYLVANIA / OIL CITY (163)	