



Date: 3/3/2023

Region: 4C
FAC ID: VA039

CSS No.: 90947
Maximo Work Order No.: 12308

Asset #: NA

Original Work Request:

Repairs needed to over crane, estimate from recommended vendor attached

Description of Repairs Needed:

Labor and material to a.) repair the crane by installing a new gear reducer b.) install a new black pendant cable using screws, retaining rotary limit cover screws, and PB screws and test for proper operation

Material List:

(4) 29298-5U Screw Captive
(4) 3317U Ring, Retaining Rotary Limit Cover Screw
(1) 42621Q Gear Reducer
(1) 26670Q Warning Label
(6) PB Screw
(22) 37226Q Pendant Cable Black
(4) 3106800-5U Hood Black

Equipment List:

Lift

PM WO History:

NA

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
30	\$4,343.98	\$2,999.30	\$7,343.28