



Facility Repair Proposal

Region: 4A
Fac ID: PA118
Date: 2/3/23

CSS # 90950
Maximo Work Order No.: 11551

Asset ID: NA

Original Work Request:

Overhead door (north side) in the warehouse is inoperable - motor continues to run and cannot be operated manually either.

Description of Repairs Needed:

Labor (approximately 4 hours) and material to a.) replace the cable back on the drum and test for proper operation.

Parts List:

Cable

Equipment List: NA

PM History:

NA

Cost Proposal:

See attached RS Means Estimate.

Total Cost: \$442.78

