



Date: 3/6/2023

Region: 4C  
FAC ID: WV022

CSS No.: 90976  
Maximo Work Order No.: 12103

Asset #: NA

**Original Work Request:**

Repair 2 glycol leaks in drill hall. 1 hanging heater and one leak coming from the piping closed.

**Description of Repairs Needed:**

Labor and material to a.) rent a lift to further diagnose the glycol leaks in the drill hall, the (1) hanging heater and the leak coming from the piping.

**Material List:**

NA

**Equipment List:**

Lift

**PM WO History:**

NA

**Estimate Summary:**

Labor Hours	Labor	Material/Equipment	Total Repair
12	\$1,666.88	\$444.26	\$2,111.14