



Date: 4/12/2023

Region: 4C
FAC ID: WV022

CSS No.: 90976
Maximo Work Order No.: 12103

Asset #: NA

Original Work Request:

Repair 2 glycol leaks in drill hall. 1 hanging heater and one leak coming from the piping closed.

Description of Repairs Needed:

Labor and material to a.) rent a lift to further diagnose the glycol leaks in the drill hall, the (1) hanging heater and the leak coming from the piping.

Material List:

NA

Equipment List:

Lift

PM WO History:

NA

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
4	\$542.72	\$1,050.00	\$1,592.72