

Facility Repair Proposal

Region: 4A
Fac ID: PA027
Date: 12/28/22

CSS # 91342
Maximo Work Order No.: 11761

Asset ID: NA

Original Work Request:
Burst Pipe Women's Restroom Shower (Emergency Response)

Description of Repairs Needed:
Labor (8) hours and material to a.) burst Pipe in Building 2 Women's Restroom Shower

Parts List:
Greenrock Drywall

Tile

Hot Water Actuator

Equipment List:
NA

PM History:
NA

Cost Proposal:
See attached RS Means Estimate.

Total Cost: \$1420.64

Estimate Name: CSS 91342 - WO 11761 - VA051 Burst Pipe Womens Restroom

ESTIMATE INFORMATION

Client Name: 99th
Estimate Address: 1915 Roanoke Boulevard, Salem, VA 24153-6408
Type: Unit
Measurement System: US Standard
Notes:

COST DATA

Estimate Summary:						Catalog: Facilities and Commercial Renovation	
						Format: MasterFormat 2018	
						Release: Year 2022 Quarter 4	
						Labor Type: Repair & Remodeling	
						City Cost Index: VIRGINIA / ROANOKE (240-241)	