



Date: 3/3/2023

Region: 4A
FAC ID: NY052

CSS No.: 91463
Maximo Work Order No.: 11805

Asset #: NA

Original Work Request:

Repairs circulating pump to zone 3 circulating pump. Circulating pump keeps tripping out.

Description of Repairs Needed:

Labor and material to a.) isolate the pump unhook the electric remove the pump b.) install the new pump reconnect the electric and test for leaks and proper operation

Material List:

(1) ARMSTRONG CIRCULATOR ARM105015B (S4012920)
.33HP 1PH 115V ODP STD

Equipment List:

NA

PM WO History:

NA

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
10	\$1,303.97	\$3,825.44	\$5,129.41

**MAINTENANCE
RECORD**

DATE BY DATE BY

W1992-01
Asset #7097 circ pump

**MAINTENANCE
RECORD**

DATE BY DATE BY

HEATING HOT WTR. SUP. 3
ZONE 3