



Date: 3/13/2023

Region: 4C
FAC ID: WV009

CSS No.: 91594
Maximo Work Order No.: 12285

Asset #: NA

Original Work Request:

Repair Exhaust fan for the welding bay, fan is located on the roof.

Description of Repairs Needed:

Labor and equipment to a.) investigate the Exhaust fan for the welding bay that's located on the roof.

Material List:

NA

Equipment List:

Lift

PM WO History:

NA

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
8	\$1,310.74	\$606.80	\$1,917.54