



Facility Repair Proposal

Region: 4A
Fac ID: NY030
Date: 2/8/23

CSS # 91731
Maximo Work Order No.: 12050

Asset ID: NA

Original Work Request:
Repair 1 inch backflow device which has failed inspection.

Description of Repairs Needed:
Labor (approximately 5 hours) and material to a.) remove the existing backflow b.) install a new backflow and test for proper operation. This will include the initial backflow test for certification.

Parts List:

Reduced Pressure Zone Backflow Preventer WATTS 1 LF909-QT

Equipment List: NA

PM History:
NA

Cost Proposal:
See attached RS Means Estimate.

Total Cost: \$2449.76

Estimate Name: CSS 91731 - WO 12050 - NY030 Repair 1" BFP

ESTIMATE INFORMATION

Client Name: 99th
Estimate Address: 3126 Upper Lake Road, Horseheads, NY 14845-3103
Type: Unit
Measurement System: US Standard
Notes:

COST DATA

Estimate Summary:						Catalog: Facilities and Commercial Renovation	
						Format: MasterFormat 2018	
						Release: Year 2023	
						Labor Type: Repair & Remodeling	
						City Cost Index: NEW YORK / ELMIRA (148-149)	

1" 909 QT

RPZ

WATTS

www.watts.com
Andover, MA 01810



B64.4

140°F 175 PSI

993