



Date: 3/6/2023

Region: 4C
FAC ID: WV022

CSS No.: 91854
Maximo Work Order No.: 12111

Asset #: NA

Original Work Request:

Failed Back Flow Preventer, needs rebuilt and retested in Training building.

Description of Repairs Needed:

Labor and material to a.) rebuild and retest the backflow in the training building RK34-975XLR
WILKN 3/4-1" 975XL RT RK34-975XLC 3/4-1" 975XL

Material List:

RK34-975XLR WILKN 3/4-1" 975XL RT
RK34-975XLC 3/4-1" 975XL

Equipment List:

NA

PM WO History:

NA

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
10	\$1,388.27	\$790.77	\$2,179.04