



Date: 3/3/2023

Region: 4C

FAC ID: WV029

CSS No.: 91855

Maximo Work Order No.: 12295

Asset #: NA

Original Work Request:

Rebuild and retest failed Back Flow Preventer.

Description of Repairs Needed:

Labor and material to a.) rebuild and retest the backflow preventer (1) 794070 WATTS 1 1/4-2" LFRK 909M1 RT (1) 794071 WATTS 1 1/4-2" LFRK 909M1 T

Material List:

(1) 794070 WATTS 1 1/4-2" LFRK 909M1 RT
(1) 794071 WATTS 1 1/4-2" LFRK 909M1 T

Equipment List:

NA

PM WO History:

NA

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
10	\$1,486.98	\$1,695.75	\$3,182.73