



Date: 3/6/2023

Region: 4C  
FAC ID: WV046

CSS No.: 91886  
Maximo Work Order No.: 12107

Asset #: NA

**Original Work Request:**

The light on main door of AMSA on left of building is burned out, also in janitors closet burned out, and bay 4 of vehicle maintenance bay the emergency light doesn't work.

**Description of Repairs Needed:**

During our initial investigation we were able to replace two emergency lights. However, a lift is needed to assess the additional lights. Labor, material, and equipment needed to continue investigating

**Material List:**

Light - LED  
Wall Pack LED

**Equipment List:**

Lift

**PM WO History:**

NA

**Estimate Summary:**

Labor Hours	Labor	Material/Equipment	Total Repair
8	\$997.04	\$444.26	\$1,441.30