



Date: 3/6/2023

Region: 4C  
FAC ID: WV035

CSS No.: 91982  
Maximo Work Order No.: 12333

Asset #: NA

#### Original Work Request:

Failed the hood inspection because canisters are over life cycle and they need to be replaced, the hood nozzles also need changed.

#### Description of Repairs Needed:

Labor and material to a.) service the fire suppression system b.) replace the A17492 Ansul Cartridge 101-20 c.) add Ansul SS 3 Gal Tank (Hydro/Refill)

#### Material List:

A17492 Ansul Cartridge 101-20  
Ansul SS 3 Gal Tank (Hydro/Refill)

#### Equipment List:

NA

#### PM WO History:

NA

#### Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
12	\$1,656.00	\$432.00	\$2,088.00