



Date: 3/22/2023

Region: 4C
FAC ID: WV009

CSS No.: 92016
Maximo Work Order No.: 12109

Asset #: NA

Original Work Request:

Motor assembly for the Wash Bay door needs replaced - it keeps vibrating and not letting the wash bay.

Description of Repairs Needed:

Labor and material to a.) Replace Fabra Photo Eyes and brace, for the Lift Master H-50-11 Operator

Material List:

Pair Fabra Photo Eyes
Piece Commercial Angle

Equipment List:

Lift

PM WO History:

NA

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
8	\$999.64	\$828.80	\$1,828.44