



Date: 3/23/2023

Region: 4C

FAC ID: WV009

CSS No.: 92018

Maximo Work Order No.: 12121

Asset #: NA

Original Work Request:

Repair exhaust fan in tool room, repair urinal downstairs and roll up extension cord in Bay 9 needs

Description of Repairs Needed:

During our initial investigation we were able to repair exhaust fan in tool room and the repair urinal downstairs. However, a lift is needed to further investigate the roll up extension cord in Bay 9.

Material List:

NA

Equipment List:

Lift

PM WO History:

NA

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
8	\$1,175.89	\$606.80	\$1,782.69

