



Date: 3/10/2023

Region: 4C
FAC ID: WV029

CSS No.: 92190
Maximo Work Order No.: 12304

Asset #: NA

Original Work Request:

Repair tube heater in Motor Pool wash bay. Section has rusted out and can see flame. Unit is turned off for now.

Description of Repairs Needed:

Labor to a.) investigate the repair of the tube heater in the Motor Pool Wash Bay.

Material List:

NA

Equipment List:

Lift

PM WO History:

NA

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
8	\$1,185.04	\$606.84	\$1,791.88