



Date: 3/2/2023

Region: 4C  
FAC ID: WV046

CSS No.: 92210  
Maximo Work Order No.: 12297

Asset #: 7142

**Original Work Request:**

Hot water circulating pump on domestic hot water not getting hot water to kitchen

**Description of Repairs Needed:**

Labor and material to a.) replace the circulating pump (Bronze 1/25 HP 115V 1PH NPTF)

**Material List:**

(1) Bronze 1/25 HP 115V 1PH NPTF

**Equipment List:**

NA

**PM WO History:**

11722

**Estimate Summary:**

Labor Hours	Labor	Material/Equipment	Total Repair
3	\$343.06	\$926.97	\$1,270.03

