



Date: 3/21/2023

Region: 4C
FAC ID: WV010

CSS No.: 92400
Maximo Work Order No.: 12350

Asset #: 6803

Original Work Request:

investigated the ice machine at WV010, the board is bad and needs replaced

Description of Repairs Needed:

Labor and material to a.) replace the board on the ice machine (Hoshizaki, 2A1410-02)

Material List:

(1) Hoshizaki, 2A1410-02

Equipment List:

NA

PM WO History:

12315

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
4	\$546.98	\$775.56	\$1,322.54

