



Date: 5/1/2023

Region: 4C
FAC ID: WV035

CSS No.: 87316
Maximo Work Order No.: 11807

Asset #: NA

Original Work Request:

4 Wall PTACS in the training building are not operating, need verification if they can be fixed or need to be replaced.

Description of Repairs Needed:

Labor and material to a.) troubleshoot and diagnose the (4) wall PTAC Units on the first unit we used the service tool and tried running unit in test mode but the unit would not run. b.) on the second unit we tested power and then pulled the board out to hook up the service tool and then ran the unit in test mode everything was working properly but the actuator for the hot water valve. c.) on the third unit we hooked up service tools and ran the unit in test mode and everything came on and unit checked out good. d.) on the 4th unit the PTAC checked out and is in working condition.

Material List:

NA

Equipment List:

NA

PM WO History:

NA

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
7	\$926.40	\$0.00	\$926.40