



Date: 5/26/2023

Region: 4C
FAC ID: WV007

CSS No.: 88842
Maximo Work Order No.: 12998

Asset #: NA

Original Work Request:

Repair stair treads in front and rear facility stairwells. Stair treads in both stairwells are deteriorated and in disrepair with broken and loose treads.

Description of Repairs Needed:

Labor and material to a.) to replace Stair Treads in Front/Rear Stairwells

Material List:

(12) Roppe #92, 48" Round Profile Stair Tread
(1) SPFloor – 1 gal Tread Adhesive

Equipment List:

NA

PM WO History:

NA

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
9	\$1,320.00	\$1,566.48	\$2,886.48