



Date: 3/20/2023

Region: 4C
FAC ID: WV035

CSS No.: 90111
Maximo Work Order No.: 12057

Asset #: NA

Original Work Request:

Replace the Release Valve on Apex boiler #4. it is failing due to the system being down for so long. it has made this valve fail.

Description of Repairs Needed:

Labor and material to a.) replace the pressure relief valve on Apex Boiler #4.

Material List:

(1) 10-301-10 Male Inlet Valve - HVAC INDUSTRIAL

Equipment List:

NA

PM WO History:

NA

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
4	\$207.08	\$938.41	\$1,145.49

