



Date: 4/3/2023

Region: 4C

FAC ID: WV035

CSS No.: 90112

Maximo Work Order No.: 12058

Asset #: NA

Original Work Request:

Replace HW Circulating Pump and Relief Valve

Description of Repairs Needed:

Labor and material to a.) replace the SP-2400-006RP Taco Motor - FERGUSON 10-301-10 HW Relief Valve - HVAC INDUSTRIAL and test for proper operation

Material List:

SP-2400-006RP Taco Motor - FERGUSON 10-301-10 HW Relief Valve - HVAC INDUSTRIAL

Equipment List:

NA

PM WO History:

NA

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
8	\$1,051.57	\$1,718.35	\$2,769.92