



Date: 3/1/2023

Region: 4A  
FAC ID: PA209

CSS No.: 91901  
Maximo Work Order No.: 12063

Asset #: NA

#### Original Work Request:

Repair three (3) LED pole lights in the POV. Two on the left when facing the building and one in the middle of the back side. There is a system in the mechanical room that will turn the lights on during the day to indicate which are not working.

#### Description of Repairs Needed:

Labor and material to a.) repair (3) parking lot lights using (3) mogul sockets, (3) retrofit lamps, fuse holders and wire.

#### Material List:

(3) Retrofit Lamps  
(3) Mogul Sockets  
(1) Fuse Holders  
(3) Fuses  
(1) #12 THWN Wire

#### Equipment List:

(1) Bucket Truck

#### PM WO History:

NA

#### Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
12	\$1,566.63	\$1,728.84	\$3,295.47



