



Date: 3/23/2023

Region: 4C
FAC ID: VA012

CSS No.: 91371
Maximo Work Order No.: 12047

Asset #: NA

Original Work Request:

AMSA center seems to have lost a phase or a breaker switch is faulty or blown. #16 on box 1. and the square D box seems to be tripping and not resetting. certain outlets within the facility and the printer are all affected.

Description of Repairs Needed:

Labor and material to a.) replace 3 phase 200amp Square D lighting contactor with new. Special part.
Please note - this part will have to be special ordered.

Material List:

3 phase 200amp Square D lighting contactor - 8903SV02

Equipment List:

NA

PM WO History:

NA

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
8	\$1,163.35	\$4,909.24	\$6,072.59