



Date: 4/3/2023

Region: 4A  
FAC ID: PA027

CSS No.: 91461  
Maximo Work Order No.: 11799

Asset #: NA

#### Original Work Request:

We have one light out in the motor pool parking lot (this needs to be repaired by next month as they have a Physical Security Inspection). In addition none of the lights in the POV are working (eight)

#### Description of Repairs Needed:

Labor and material to a.) replace (1) MEP light.

#### Material List:

Flood Light LITHONIA ESXF4

#### Equipment List:

Bucket Truck

#### PM WO History:

NA

#### Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
6	\$927.19	\$709.49	\$1,636.68