



Date: 3/15/2023

Region: 4A
FAC ID: PA118

CSS No.: 91837
Maximo Work Order No.: 12064

Asset #: NA

Original Work Request:

Repair AMSA bay overhead door #4 - opener does not work to open door, however it does to close the door.

Description of Repairs Needed:

Labor and material to a.) tighten the clutch plate b.) set limits and test for proper operation

Material List:

NA

Equipment List:

NA

PM WO History:

NA

Estimate Summary:

| Labor Hours | Labor | Material/Equipment | Total Repair |
|-------------|----------|--------------------|--------------|
| 4 | \$542.40 | \$12.00 | \$554.40 |