



Date: 4/12/2023

Region: 4C
FAC ID: WV005

CSS No.: 91857
Maximo Work Order No.: 12363

Asset #: NA

Original Work Request:

3" Watts 009 and 2" Wilkins 975XL, both Back Flow Preventers failed inspection and need to be rebuilt.

Description of Repairs Needed:

Labor to a.) replace the 3 inch back flow valve (3" Watts 009) b.) replace the 2 inch back flow valve (2" Wilkins 975XL)

Material List:

(1) (2" Wilkins 975XL)
(1) (3" Watts 009)

Equipment List:

NA

PM WO History:

NA

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
12	\$1,574.25	\$6,442.47	\$8,016.72