



Date: 3/1/2023

Region: 4C
FAC ID: WV046

CSS No.: 91915
Maximo Work Order No.: 12077

Asset #: NA

Original Work Request:

Replace bad CO detectors causing the Fire panel to go into trouble alarm.

Description of Repairs Needed:

Labor and material to a.) install and program (4) OOH C Detectors Smoke and CO.

Material List:

(4) OOH C, Siemens Detectors Smoke and CO. (OOHC941)

Equipment List:

NA

PM WO History:

NA

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
5	\$674.10	\$518.82	\$1,192.92