



Date: 4/3/2023

Region: 4A
FAC ID: PA035

CSS No.: 92161
Maximo Work Order No.: 12119

Asset #: NA

Original Work Request:

Perform PM on Fire Protection Equipment Not in Inventory

Description of Repairs Needed:

Labor to a.) inspect and certify the Captive Aire equipment associated with Kitchen Hood Suppression System b.) inspection paperwork will be provided upon completion.

Material List:

NA

Equipment List:

NA

PM WO History:

NA

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
2	\$269.10	\$0.00	\$269.10