



Date: 4/20/2023

Region: 4C
FAC ID: WV020

CSS No.: 92410
Maximo Work Order No.: 12528

Asset #: NA

Original Work Request:

Replace bearing assembly on boiler pump #2

Description of Repairs Needed:

Labor and material to a.) install (1) 1EF054LF B&G 1HP 208/230/460V 3PH Cast Iron Bronze Pump.

Please note: there is a 6-8 week lead time on this pump.

Material List:

(1) 1EF054LF B&G 1HP 208/230/460V 3PH Cast Iron Bronze Pump.

Equipment List:

NA

PM WO History:

NA

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
6	\$780.02	\$2,816.97	\$3,596.99