



Date: 4/27/2023

Region: 4C
FAC ID: WV009

CSS No.: 92485
Maximo Work Order No.: 12545

Asset #: NA

Original Work Request:

Repair air hose reel (leak) in Bay 10, Repair air regulator for antifreeze pump.

Description of Repairs Needed:

Labor and material to a.) replace the Balcrank 3260-034 Filter/Regulator

Material List:

(1) balcrank 3260-034 – Filter/reg auto drain ¼

Equipment List:

NA

PM WO History:

NA

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
5	\$511.53	\$152.44	\$663.97